

Condition Report

Model	Serial No	Year
WA380-5	62045	2006
Hourmeter	Location	
11458	Kobe center	

Rank of Machine Condition	
A	New or Rebuilt Unit
B	Good with Lapse of Years
C	Normal Operation/Appearance of Wear or Quality Down on Lapse
D	No Problem on Operation, but Repair requested
E	Quick Repair or Replacement requested

Item	Sub Item	Inspection	Machine Condition	Remarks
Engine	Engine	Whole	C	
		Oil Leakage	C	
		Water Leakage	C	
		Back Pressure	C	
		Exhaust Smoke Color	C	
		Other	C	
Power Train	Torque Converter	Whole	C	
		Oil Leakage	C	
		Other	C	
	Transmission	Whole	C	
		Oil Leakage	D	Oil leak from transmission
		Other	C	
	Propeller Shaft	Whole	C	
		Play	C	
		Other	C	
	Brake(Including Parking Brake)	Whole	C	
		Brake Function	C	
		Wear	C	
		Other	C	
	Steering Pump & Gear	Whole	C	

Condition Report

Model	Serial No	Year
WA380-5	62045	2006
Hourmeter	Location	
11458	Kobe center	

Item	Sub Item	Inspection	Machine Condition	Remarks
		Oil Leakage	C	
		Steering Function	C	
		Other	C	
	Steering Cylinder[R]	Whole	C	
		Oil Leakage	C	
		Rod	C	
		Other	C	
	Steering Cylinder[L]	Whole	C	
		Oil Leakage	C	
		Rod	C	
		Other	C	
	Axle [Front]	Whole	C	
		Oil Leakage	C	
		Noise	C	
		Breakage	C	
		Other	C	
	Axle [Rear]	Whole	C	
		Oil Leakage	C	
		Noise	C	
		Breakage	C	
		Other	C	
	Tire[R. Front]	Whole	C	
		Damage	C	
		Groove Depth	C	0mm
Tire[L. Front]	Whole	C		
	Damage	C		
	Groove Depth	C	0mm	

Condition Report

Model	Serial No	Year
WA380-5	62045	2006
Hourmeter	Location	
11458	Kobe center	

Item	Sub Item	Inspection	Machine Condition	Remarks
	Tire[R. Rear]	Whole	C	
		Damage	C	
		Groove Depth	C	0mm
	Tire[L. Rear]	Whole	C	
		Damage	C	
		Groove Depth	C	0mm
Work Unit	Operation Levers	Whole	C	
		Stick	C	
		Oil Leakage	C	
	Lift Arm	Whole	C	
		Deformation	C	
		Crack	C	
		Wear of Pin,Bush	C	
		Signs of Repair	C	
		Other	C	
	Bucket	Whole	C	
		Wear of Tooth	C	
		Wear of Bottom Plate	C	
Other		C		
Hydraulic Units	Pump	Whole	C	
		Oil Leakage	C	
	Control Valve	Whole	C	
		Oil Leakage	C	
	Lift Cylinder[R]	Whole	C	
		Oil Leakage	C	
		Rod	C	
		Other	C	

Condition Report

Model	Serial No	Year
WA380-5	62045	2006
Hourmeter		Location
11458		Kobe center

Item	Sub Item	Inspection	Machine Condition	Remarks
	Lift Cylinder[L]	Whole	C	
		Oil Leakage	C	
		Rod	C	
		Other	C	
	Bucket Cylinder[R]	Whole	C	
		Oil Leakage	C	
		Rod	C	
		Other	C	
Appearance	Operation Room Cabin Canopy	Whole	C	
		Deformation	C	
		Corrosion	C	
		Other	C	
	Covers	Whole	C	
		Deformation	C	
		Corrosion	C	
		Other	C	
	Frame	Whole	C	
		Deformation	C	
		Crack	C	
		Other	C	Center pin play
	Painting	Whole	C	
		Corrosion	C	
		Rust	C	
		Other	C	

Other

Condition Report

Model	Serial No	Year
WA380-5	62045	2006
Hourmeter	Location	
11458	Kobe center	

--