

Condition Report

Model	Serial No	Year
PC40MR-3	19332	2011
Hourmeter	Location	
2067	Kysuyu center	

Rank of Machine Condition	
A	New or Rebuilt Unit
B	Good with Lapse of Years
C	Normal Operation/Appearance of Wear or Quality Down on Lapse
D	No Problem on Operation, but Repair requested
E	Quick Repair or Replacement requested

Item	Sub Item	Inspection	Machine Condition	Remarks
Engine	Engine	Whole	C	
		Oil Leakage	C	
		Water Leakage	C	
		Back Pressure	C	
		Exhaust Smoke Color	C	
		Other	D	Fan belt excessive wear
Swing Unit	Swing Unit	Whole	C	
		Play to Swing	C	
		Swing Machinery	C	
		Other	C	
Work Unit	Operation Levers	Whole	C	
		Stick	C	
		Oil Leakage	C	
		Other	C	
	Boom(Including Off-Set)	Whole	C	
		Deformation	C	
		Crack	C	
		Wear of Pin,Bush	C	
		Signs of Repair	C	

Condition Report

Model	Serial No	Year
PC40MR-3	19332	2011
Hourmeter	Location	
2067	Kysuyu center	

Item	Sub Item	Inspection	Machine Condition	Remarks	
	Arm	Other	C		
		Whole	C		
		Deformation	C		
		Crack	C		
		Wear of Pin,Bush	C		
		Signs of Repair	C		
		Other	C		
	Bucket or Front ATT e.g., breaker	Whole	C		
		Wear of Tooth	C		
		Wear of Bottom Plate	C		
		Other	C		
	Swing	Whole	C		
		Other	C		
	Blade	Whole	C		
		Deformation	C		
		Crack	C		
		Other	C		
	Under Carriage	Sprocket[R]	Whole	C	
			Other	C	
		Sprocket[L]	Whole	C	
Other			C		
Idler[R]		Whole	C		
		Internal Play	C		
		Wear	C		
		Other	C		
Idler[L]		Whole	C		
		Internal Play	C		

Condition Report

Model	Serial No	Year
PC40MR-3	19332	2011
Hourmeter	Location	
2067	Kusyu center	

Item	Sub Item	Inspection	Machine Condition	Remarks	
		Wear	C		
		Other	C		
	Rollers	Whole	C		
		Oil Leakage, Play	C		
		Wear	C		
		Other	C		
	Track Link Ass'y	Whole	C		
		Pin Hole Wear	C		
		Height Wear	C		
		Other	C		
	Pin & Bush	Whole	C		
		Wear	C		
		Crack	C		
		Other	C		
	Steel Tracks	Whole	C		
		Breakage	C		
		Other	C		
	Hydraulic Units	Pump	Whole	C	
			Oil Leakage	C	
Other			C		
Control Valve		Whole	C		
		Oil Leakage	C		
		Other	C		
Boom Cylinder[R]		Whole	C		
		Oil Leakage	C		
		Rod	C		
		Other	C		

Condition Report

Model	Serial No	Year
PC40MR-3	19332	2011
Hourmeter	Location	
2067	Kysuyu center	

Item	Sub Item	Inspection	Machine Condition	Remarks
	Arm Cylinder	Whole	C	
		Oil Leakage	C	
		Rod	C	
		Other	C	
	Bucket Cylinder	Whole	C	
		Oil Leakage	C	
		Rod	C	
		Other	C	
	Off-Set Cylinder(Including Swing Cylinder)	Whole	C	
		Oil Leakage	C	
		Rod	C	
		Other	C	
	Swing Motor(Swivel Joint)	Whole	C	
		Oil Leakage	C	
		Other	C	
	Travel Motor[R]	Whole	C	
		Oil Leakage	C	
		Function	C	
		Other	C	
	Travel Motor[L]	Whole	C	
Oil Leakage		C		
Function		C		
Other		C		
Appearance	Operation Room Cabin Canopy	Whole	C	
		Deformation	C	
		Corrosion	C	

Condition Report

Model	Serial No	Year
PC40MR-3	19332	2011
Hourmeter	Location	
2067	Kususyu center	

Item	Sub Item	Inspection	Machine Condition	Remarks
		Other	C	
	Covers	Whole	C	
		Deformation	C	
		Corrosion	C	
		Other	C	
	Frame	Whole	C	
		Deformation	C	
		Crack	C	
		Other	C	
	Painting	Whole	C	
		Corrosion	C	
		Rust	C	
		Other	C	

Other